

Curing times

RSB Temperature at anchoring base [°C]	Minimum curing time RSB	
	t_{cure} [hrs.]	[min.]
-30 – -20 ¹⁾	120	–
> -20 – -15	48	–
> -15 – -10	30	–
> -10 – -5	16	–
> -5 – 0	10	–
> +0 – +5	–	45
> +5 – +10	–	30
> +10 – +20	–	20
> +20 – +30	–	5
> +30 – +40	–	3

1) Minimum resin capsule temperature -15°C