## **Curing times**

+20 - +30

+30 - +40

| FIS P 300 T                    |                         |                               |                     |        |
|--------------------------------|-------------------------|-------------------------------|---------------------|--------|
| Cartridge temperature (mortar) | Maximum processing time | Temperature at anchoring base | Minimum curing time |        |
|                                | t <sub>work</sub>       |                               | t <sub>cure</sub>   |        |
| [°C]                           | [min.]                  | [°C]                          | [hrs.]              | [min.] |
|                                |                         | 0 – +5                        | 6                   | -      |
| +5 - +10                       | 15                      | +5 - +10                      | 3                   | -      |
| +10 - +20                      | Q                       | +10 - +20                     | 2                   |        |

+20 - +30

+30 - +40

60

30

+10 - +20+10 - +20

For installation, the cartridge temperature must be at least +5 °C. For longer installation times, i.e. when interruptions occur in work, the mixer should be replaced.

The above times apply from the moment of contact between resin and hardener in the static mixer.