

Aushärtezeiten

RM II Temperatur im Verankerungsgrund [°C]	Minimale Aushärtezeit t_{cure}	
	[Std.]	[Min.]
-15 – -10	30	–
> -10 – -5	16	–
> -5 – 0	10	–
> 0 – +5	–	45
> +5 – +10	–	30
> +10 – +20	–	20
> +20 – +30	–	5
> +30 – +40	–	3